

# BIOS Release Notes

## TITLE

---

**SUBJECT:** MS93-FS0 BIOS Release Notes version [R11](#)

**System:** [MS93-FS0-000](#), [R183-S90-AAD1-000](#), [R183-S90-LAD1-000](#), [R183-S90-AAD2-000](#), [R183-S90-AAV1-000](#), [R183-S90-IAV1-000](#), [R183-S90-AAV2-000](#), [R183-S91-AAD1-000](#), [R183-S91-AAD2-000](#), [R183-S91-AAV1-000](#), [R183-S91-AAV2-000](#), [R183-S92-AAD1-000](#), [R183-S92-AAD2-000](#), [R183-S92-AAD3-000](#), [R183-S92-AAV1-000](#), [R183-S92-AAV2-000](#), [R183-S92-AAV3-000](#), [R183-S95-AAD1-000](#), [R183-S95-AAV1-000](#), [R183-S96-AAD1-000](#), [R183-S96-AAV1-000](#), [R183-S97-AAD1-000](#), [R183-S97-AAV1-000](#), [R283-S90-AAE1-000](#), [R283-S90-AAE2-000](#), [R283-S90-AAE3-000](#), [R283-S90-AAJ1-000](#), [R283-S90-AAJ2-000](#), [R283-S90-AAJ3-000](#), [R283-S91-AAE1-000](#), [R283-S91-AAE2-000](#), [R283-S91-AAJ1-000](#), [R283-S91-AAJ2-000](#), [R283-S92-AAE1-000](#), [R283-S92-AAE2-000](#), [R283-S92-AAE3-000](#), [R283-S92-AAE4-000](#), [R283-S92-AAJ1-000](#), [R283-S92-AAJ2-000](#), [R283-S92-AAJ3-000](#), [R283-S92-AAJ4-000](#), [R283-S96-AAE1-000](#), [R283-S96-AAJ1-000](#), [R283-S97-AAD1-000](#), [R283-S97-AAV1-000](#), [R283-S98-AAE1-000](#), [R283-S98-AAE2-000](#), [R283-S98-AAJ1-000](#), [R283-S98-AAJ2-000](#), [E283-S90-AAD1-000](#), [E283-S90-AAV1-000](#)

---

### About This Release

**Build Date:** [2025/02/06](#)

**BIOS Checksum:** [0xA4AF4EFF](#) (16M), [0x8CB6245C](#) (64M)

**Release Owner:** jim.huang

### BIOS Components/Contents

**Processor stepping(s) supported:** Intel® Sapphire Rapids-SP/Emerald Rapids-SP processor

**System hardware configurations supported:** MS93-FS0

**Microcode updates versions:**

CPUID	Family	Microcode Update ID
806f3	Sapphire Rapids Production D-0	0d0004b1
806f8	Sapphire Rapids All HBM Production B	2c0003e0

## BIOS Release Notes

806f8	Sapphire Rapids All Production XCC E / MCC S / EE LCC U	2b000620
c06f2	Processor Emerald Rapids Production XCC A1 / MCC R1	21000291

**IPMI support:**

**AMI Kernel version:** Gbt\_Kernel\_107\_41

**Intel CSI/MRC Package version:** 113.D55

**SPI Descriptor version:** 06.01.04.075.0

**OPROM version :**

OPROM	Version
INTEL 1G PXE	1.5.53
INTEL 1G LAN EFI	8.5.21
AST2600 VGA	1.13.03
INTEL RAID PACKAGE	RSTe 8.6.0.1136

## Installation Notes

### IMPORTANT NOTES:

1. Please extract the MS93-FS0\_R11.zip to a bootable diskette that use FAT/FAT32 format

### BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

### BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.

Or

# BIOS Release Notes

Enter \Tool\Win64 and execute f.bat for Windows 64bit.

4. After bios flash finish, system must Power-Off to have the changes take effect.

## BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

## BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press <DEL> during POST
2. The bios version shows on the first main page

## Known Issues/Workarounds

## Issues fixed in this version

R11

1. [Feature] Fine-tune Redfish display content.

R10

1. [Feature] Update RC 113.D55 (EagleStream uPLR3 BKC 2024 WW37).
2. [Feature] Update EMR Microcode : EMR Production A\* / R\* Step: m\_87\_c06f2\_21000291.pdb;
3. [Feature] Update SPR Microcode : SPR Production E\* / S\* Step: m\_87\_806f8\_2b000620.pdb; SPR HBM Production B\* Step: m\_10\_806f8\_2c0003e0.pdb;
4. [Feature] Include INTEL-SA-01139 for CVE-2024-31157/CVE-2024-28047/CVE-2024-39279.
5. [Feature] Include INTEL-SA-01166 for CVE-2024-31068.
6. [Feature] Include INTEL-SA-01194 for CVE-2024-37020.
7. [Feature] Include INTEL-SA-01120 for CVE-2024-25571.
8. [Feature] Include INTEL-SA-01198 for CVE-2024-21859/CVE-2024-31155.
9. [Feature] Include INTEL-SA-01152 for CVE-2024-26021/CVE-2024-30211.
10. [Feature] Include INTEL-SA-01196 for CVE-2024-36242.
11. [Feature] Include INTEL-SA-01192 for CVE-2024-33607.

R09

1. [Feature] Update RC 111.D23 (EagleStream uPLR2 BKC 2024 WW30).
2. [Feature] Update EMR Microcode : EMR Production A\* / R\* Step: m\_87\_c06f2\_21000283.pdb;
3. [Feature] Update SPR Microcode : SPR Production E\* / S\* Step:

## BIOS Release Notes

m\_87\_806f8\_2b000603.pdb;SPR HBM Production B\* Step: m\_10\_806f8\_2c0003d3.pdb;

4. [Feature] Update UEFI VROC to VROC v8.6.0.1136.
  5. [Feature] Update TDX Module to TDX\_1.5.06.00.744.
  6. [Bug Fix] Include INTEL-SA-01097 for CVE-2024-24968.
  7. [Bug Fix] Include INTEL-SA-01103 for CVE-2024-23984.
  8. [Bug Fix] Include INTEL-SA-01079 for CVE-2024-21820/CVE-2024-23918.
  9. [Bug Fix] Include INTEL-SA-01071 for CVE-2024-21829/CVE-2024-21781/CVE-2024-23599.
  10. [Bug Fix] Include INTEL-SA-01085 for CVE-2024-25565.
  11. [Bug Fix] Include INTEL-SA-01101 for CVE-2024-21853.
  12. [Bug Fix] Include INTEL-SA-01099 for CVE-2024-27457.
  13. [Bug Fix] Include INTEL-SA-01111 for CVE-2024-22185/CVE-2024-24985.
  14. [Bug Fix] Include INTEL-SA-01076 for CVE-2024-21850.
  15. [Bug Fix] Include AMI SA50158 for CWE-269.
- 

### R08

1. [Feature] Update RC 109.D34 (EagleStream uPLR1 OOB BKC 2024).
  2. [Feature] Update EMR Microcode : EMR Production A1/R1-Stepping:m\_87\_c06f2\_21000240.pdb;
  3. [Feature] Update SPR Microcode : SPR Production E-Stepping:m\_87\_806f8\_2b0005d1.pdb;SPR HBM Production B-Stepping:m\_10\_806f8\_2c0003a1.pdb;
  4. [Feature] Fine tune BMC LAN IPv6 configuration page.
- 

### R07

1. [Feature] Fine tune Intel TDX related item.
  2. [Feature] Fine tune BMC IPv6 and IPv4 Network.
  3. [Feature] Include AMI SA50248 solution for CWE-119.
- 

### R06

1. [Feature] Update RC 109.D34 (EagleStream uPLR1 BKC 2024 WW12).
2. [Feature] Update EMR Microcode : EMR Production A1/R1-Stepping:m\_87\_c06f2\_21000230.pdb;
3. [Feature] Update SPR Microcode : SPR Production E-Stepping:m\_87\_806f8\_2b0005c0.pdb;SPR HBM Production B-Stepping:m\_10\_806f8\_2c000390.pdb;
4. [Feature] Update SPS FW to SPS\_E5\_06.01.04.047.0.
5. [Feature] Update BIOS ACM / SINT to v1.1.A.
6. [Feature] Update TDX Module to TDX\_1.5.05.46.698.
7. [Feature] Include INTEL-TA-01036 for CVE-2023-45745/CVE-2023-47855.
8. [Feature] Include AMI SA50232 for CVE-2023-45236/CVE-2023-45237.

# BIOS Release Notes

---

## R05

1. [Bug Fix] Fix install CMT4032 can't downgrade to Gen3.
- 

## R04

1. [Feature] Update RC 1752.P05 (EagleStream UMR1 BKC 2024 WW05).
  2. [Feature] Update EMR Microcode : No update.
  3. [Feature] Update SPR Microcode : SPR Production E-Stepping:m\_87\_806f8\_2b000590.pdb;SPR HBM Production B-Stepping:m\_10\_806f8\_2c000360.pdb;
  4. [Feature] Add AMI SA50218 for below CVE :  
CVE-2023-45229  
CVE-2023-45230  
CVE-2023-45231  
CVE-2023-45232  
CVE-2023-45233  
CVE-2023-45234  
CVE-2023-45235
  5. [Feature] Add AMI SA50229 for CVE-2023-3817 and CVE-2023-2650.
  6. [Feature] Add AMI SA50236 for CVE-2023-5678.
- 

## R03

1. [Feature] Update RC 107.D52 (EagleStream PV BKC 2023 WW49).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000200.pdb ; EMR Production A0-Stepping:Stepping:m\_87\_c06f2\_21000200.pdb;
  3. [Feature] Add AMI SA50216 solution for CVE-2023-39539 and CVE-2023-39538.
- 

## R02

1. [Feature] Modify the Best Performance Profile.
- 

## R01

1. [Feature] Update RC 107.D20 (EagleStream BKC 2023 WW45).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a10001d1.pdb .pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_210001B0.pdb; SPR Production E-Stepping:m\_87\_806f8\_2b000571.pdb;SPR HBM Production B-Stepping:m\_87\_806f8\_2c000351.pdb;
  3. [Feature] Update SPS to SPS\_E5\_06.01.04.005.0.
  4. [Feature] Update RSTe VROC driver to v8.5.0.1096.
- 

## T08

## BIOS Release Notes

1. [Bug Fix] Fix ES EMR CPU can't power on.
- 

### T07

1. [Feature] Update RC 105.D74 (EagleStream BKC 2023 WW41).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000190.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000190.pdb; SPR Production E-Stepping:m\_87\_806f8\_2b000541.pdb;SPR HBM Production B-Stepping:m\_87\_806f8\_2c000321.pdb;
  3. [Feature] Update SPS to SPS\_E5\_06.01.04.003.0.
  4. [Feature] Update AST2600 vga/dp driver to 1.13.03 version.
- 

### T06

1. [Feature] Base on 2023 WW37 BKC release PC version BIOS.
- 

### T05

1. [Feature] Update RC 105.D74 (EagleStream BKC 2023 WW37).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000161.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000161.pdb;
- 

### T04

1. [Feature] Update RC 105.D48 (EagleStream BKC 2023 WW35).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000160.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000160.pdb;
  3. [Feature] Update VROC driver to v8.5.0.1074
- 

### T03

1. [Feature] Update RC 105.D20 (EagleStream BKC 2023 WW33).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000150.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000140.pdb;
  3. [Feature] Update EMR SPS version to SPS\_E5\_06.01.03.011.0.
- 

### T02

1. [Feature] Update RC 103.D70 (EagleStream BKC 2023 WW27).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000100.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_210000e0.pdb;
  3. [Feature] Update EMR SPS version to SPS\_E5\_06.01.02.048.0.
  4. [Feature] Update VROC driver to v8.5.0.1042.
- 

### T01

1. [Feature] Update RC 102.D37 (EagleStream BKC 2023 WW21).

## BIOS Release Notes

2. [Feature] Update EMR Microcode : EMR A0-Stepping: EMR A0-Stepping:  
m\_87\_c06f2\_a10000a0.pdb ; EMR Production A0-Stepping:m\_87\_c06f1\_21000070.pdb;
  3. [Feature] Update EMR SPS version to SPS\_E5\_06.01.02.009.0.
  4. [Feature] Update VROC driver to v8.5.0.1020.
-