

BIOS Release Notes

TITLE

SUBJECT: MA34-CP0 BIOS Release Notes version [F09](#)

System: [MA34-CP0-000](#)

About This Release

Build Date: [2024/11/26](#)

BIOS Checksum: [0xB94942A0](#) (16M), [0x57A64283](#) (64M)

Release Owner: jim.yang

BIOS Components/Contents

Processor stepping(s) supported: IntelR Granite Rapids-AP, Sierra Forest-AP processor

System hardware configurations supported: MA34-CP0

Microcode updates versions:

CPUID	Family	Microcode Update ID
a06d0	Processor GNR A0	10000680
a06d1	Processor GNR B0	01000311
a06f3	Processor SRF C0	83000270

IPMI support:

AMI Kernel version: [Gbt_Kernel_064_27](#)

Intel CSI/MRC Package version: [3544P.08](#)

OPROM version :

OPROM	Version
INTEL 1G PXE	1.5.53
INTEL 1G LAN EFI	8.5.21
AST2600 VGA	1.13.05
INTEL RAID PACKAGE	RSTe 9.0.0.1230

BIOS Release Notes

Installation Notes

IMPORTANT NOTES:

1. Please extract the MA34-CP0_F09.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.
Or
Enter \Tool\Win64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

Issues fixed in this version

F09

1. [Feature] Update VR solution : B5

F08

1. [Bug Fix] Fix the bug about device resource related function.

BIOS Release Notes

2. [Feature] Update AST2600 driver : 1.13.05
 3. [Feature] Update VR solution : B4
-

F07

1. [Feature] Update RC 3544P.08 (BKC 2024 WW43)
 2. [Feature] Update microcode:
GNR A0 MCU : m_95_a06d0_10000680
GNR B0 MCU : m_95_a06d1_01000311
SRF C0 MCU : m_01_a06f3_83000270
 3. [Feature] Update Mapping table : R08
 4. [Feature] Update VR solution : B3
-

F06

1. [Bug Fix] Add intel patch for preventing boot failed with Samsung's specific dimms.
 2. [Bug Fix] Fix the bug about system will hang code after changing slot lanes.
 3. [Feature] Update Mapping table : R07
-

F05

1. [Feature] Support BHS-AP GNR PRQ/QS CPU.
-

F04

1. [Feature] Update RC 34.D65 (BKC 2024 WW33)
 2. [Feature] Update microcode:
GNR A0 MCU : m_95_a06d0_80000670
GNR B0 MCU : m_95_a06d1_810002e0
SRF C0 MCU : m_01_a06f3_83000211
 3. [Feature] VROC driver : 9.0.0.1230
 4. [Bug Fix] Fix the bug about incorrect ECC CE/UCE sel information.
-

F03

1. [Bug Fix] Fixed ECC CE & UCE SEL log incorrect location.
-

F02

1. [Feature] Unhide below items:
Chipset-> UPI Configuration-> Uncore General Configuration-> Directory Mode Enable
Chipset-> UPI Configuration-> Uncore General Configuration-> Link L0p Enable
-

F01

1. [Feature] First PVT release BIOS.
-

BIOS Release Notes

D14

1. [Bug Fix] Fix the bug about specific NVMe port hotplug fail.
-

D13

1. [Bug Fix] Fix the bug about PCIe device out of resource.
-

D12

1. [Bug Fix] Fix SVID/SSID programming issue, some of them are write before OEM take action.
 2. [Feature] Adjust BIOS setup menu page "Processor Configuration", add TME state output texts.
-

D11

1. [Feature] Support dual BIOS check command.
 2. [Bug Fix] Fix the bug about remote setup error.
 3. [Bug Fix] Fix the ECC/PERR/SERR incorrect format.
-

D10

1. [Feature] Update Ti VR binary to version "B2", signature "J1FE".
-

D09

1. [Feature] Update RC 3218.D03 (BKC 2024 WW21)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_80000640
SRF C0 MCU : m_01_a06f3_13000132
 3. [Feature] VROC driver : 9.0.0.1230
 4. [Bug Fix] Fix the bug about BIOS recovery feature.
 5. [Bug Fix] Fix the bug about incorrect remote setup menu information.
-

D08

1. [Bug Fix] Fix slot PCIE_1 and PCIE_2 of "MA34-CP0-000" do not trigger auto bifurcation mechanism correctly.
-

D07

1. [Feature] Update RC 0031.D97 (BKC 2024 WW19)
2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_80000640
SRF C0 MCU : m_01_a06f3_13000132
3. [Feature] VROC driver : 9.0.0.1230

BIOS Release Notes

4. [Bug Fix] Fix the yellow device of com port.
-

D06

1. [Feature] Support dual BIOS check command.
 2. [Feature] Support ROT region & BIOS information.
 3. [Feature] Update BHS-AP VROC EFI driver to 9.0.0.1230 version.
-

D05

1. [Bug Fix] Fixed USB ports show incorrect info.
-

D04

1. [Bug Fix] Fix missing security related BIOS setup items.
 2. [Bug Fix] Fix boot order is not flushed after AFU update.
 3. [Bug Fix] Fix production signed ACTM firmware is not included properly, causing indefinite reboot if SGX is activated.
 4. [Feature] Enable KMIP feature.
-

D03

1. [Feature] Update mapping table to version "05".
-

D02

1. [Feature] Update mapping table to version "04".
-

D01

1. [Feature] Enter DVT stage.
-

E16

1. [Feature] Support Power Policy setup item.
-

E15

1. [Feature] Turn on VR programming for Ti VR with binary version "B1", signature is "J0FE".
 2. [Feature] Update mapping table to version "03".
-

E14

1. [Bug Fix] Fix the bug about hanging code at 0x92 during VMD enable.
-

E13

1. [Feature] Update mapping table to version "02", adding BPB region.
-

E12

BIOS Release Notes

1. [Feature] Update RC 0031.D27 (BKC 2024 WW15)

2. [Feature] Update microcode:

SRF A0 MCU : m_01_a06f0_80000360

GNR A0 MCU : m_01_a06f0_80000620

SRF C0 MCU : m_01_a06f3_13000132

3. [Feature] VROC driver : 9.0.0.1088

E11

1. [Feature] Update RC 0030.D85 (BKC 2024 WW13)

2. [Feature] Update microcode:

SRF A0 MCU : m_01_a06f0_80000360

GNR A0 MCU : m_01_a06f0_80000611

SRF C0 MCU : m_01_a06f3_13000131

3. [Feature] VROC driver : 9.0.0.1088

E10

1. [Feature] Add MB redriver program commands and enable redriver programming.

E09

1. [Bug Fix] Fine tune release note information.

E08

1. [Feature] Fine tune WOL default setting to "Enable".

2. [Bug Fix] Fix SMBIOS Type 16 incorrect information.

3. [Feature] Support "Power Button 1s shutdown" function under OS.

4. [Bug Fix] Fix IPV6 setting bug.

5. [Bug Fix] Fix ECC information during POST.

6. [Bug Fix] Fix NVMe port number incorrect in POST Text phase with VMD enable.

7. [Bug Fix] Fix Main page "Processor" incorrect information.

8. [Bug Fix] Fix ECC Bad DIMM will disappear after UCE occur.

9. [Bug Fix] Fix SMBIOS Type 129 incorrect information.

E07

1. [Feature] Support SRF QS C0 stepping CPU.

E06

1. [Feature] Update kernel 5.34_0ACQZ_30D54_SRFSP_48_BETA

2. [Feature] Update RC 0030.D54 (BKC 2024 WW11)

3. [Feature] Update microcode:

SRF A0 MCU : m_01_a06f0_80000360

BIOS Release Notes

GNR A0 MCU : m_01_a06f0_80000600

4. [Feature] VROC driver : 9.0.0.1088

E05

1. [Feature] Implement USB mapping.

E04

1. [Bug Fix] Fix auto bifurcation config error.

E03

1. [Bug Fix] Fix LAN disable error.

E02

1. [Feature] Update RC 0030.D34 (BKC 2024 WW09).

2. [Feature] Update microcode:

SRF A0 MCU : m_01_a06f0_80000360

GNR A0 MCU : m_01_a06f0_80000595

3. [Feature] VROC driver : 9.0.0.1096

E01

1. [Feature] First release.
