

BIOS Release Notes

TITLE

SUBJECT: MA94-FS0 BIOS Release Notes version [F04](#)

System: [MA94-FS0-000](#), [R284-A90-AAL2-000](#), [R184-A92-AAJ1-000](#), [R284-A90-AAL2-GB0](#), [R184-A90-AAJ1-000](#), [R284-A90-AAL1-000](#), [R284-A94-AAL1-000](#), [R284-A93-AAL1-000](#), [R284-A94-AAL1-GB0](#), [R284-A91-AAL1-000](#), [R284-A92-AAL2-000](#), [R184-A91-AAJ1-000](#), [R184-A93-AAJ1-000](#), [R284-A92-AAL1-000](#), [E284-A90-AAJ1-000](#), [R284-A92-AAL2-GB0](#), [R184-A91-AAJ1-GB0](#), [R184-A93-AAJ1-GB0](#), [MA94-FS0-00A](#), [R284-A93-AAS1-000](#), [R184-A92-LAJ1-000](#)

About This Release

Build Date: [2024/09/03](#)

BIOS Checksum: [0xBC775046](#) (16M), [0x5AD429D9](#) (64M)

Release Owner: willy.chen

BIOS Components/Contents

Processor stepping(s) supported: Intel® Granite Rapids-AP, Sierra Forest-AP processor

System hardware configurations supported: MA94-FS0

Microcode updates versions:

CPUID	Family	Microcode Update ID
a06d0	Processor GNR A0	80000670
a06d1	Processor GNR B0	810002e0
a06f3	Processor SRF C0	83000211

IPMI support:

AMI Kernel version: [Gbt_Kernel_059_05](#)

Intel CSI/MRC Package version: [34.D65](#)

OPROM version :

OPROM	Version
AST2600 VGA	1.12.00

BIOS Release Notes

INTEL RAID PACKAGE	RSTe 9.0.0.1230
-----------------------	-----------------

Installation Notes

IMPORTANT NOTES:

1. Please extract the MA94-FS0_F04.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.
Or
Enter \Tool\Win64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

Issues fixed in this version

F04

1. [Feature] Update RC 34.D65 (BKC 2024 WW33)
2. [Feature] Update microcode:

BIOS Release Notes

GNR A0 MCU : m_95_a06d0_80000670

GNR B0 MCU : m_95_a06d1_810002e0

SRF C0 MCU : m_01_a06f3_83000211

3. [Feature] VROC driver : 9.0.0.1230

4. [Bug Fix] Fix the bug about incorrect ECC CE/UCE sel information.

F03

1. [Bug Fix] Fixed ECC CE & UCE SEL log incorrect location.

F02

1. [Feature] Unhide below items:

Chipset-> UPI Configuration-> Uncore General Configuration-> Directory Mode Enable

Chipset-> UPI Configuration-> Uncore General Configuration-> Link L0p Enable

F01

1. [Feature] The first PVT release BIOS.

D19

1. [Feature] Support SRF-AP C0-stepping CPU.

2. [Bug Fix] Fixed bug about showing incorrect USB port info.

3. [Bug Fix] Fix incompliant uCode token name.

4. [Feature] Update SRF uCode to ESx C-0 stepping.

5. [Bug Fix] Fixed USB asl code hub status reporting error issue.

D18

1. [Bug Fix] Fix the bug about specific NVMe port hotplug fail.

D17

1. [Bug Fix] Fix the bug about PCIE device out of resource.

D16

1. [Feature] Support SRF PRQ C0 stepping CPU.

D15

1. [Bug Fix] Fix the bug about incorrect SVID.

D14

1. [Feature] Update VR TI version : B4.

2. [Feature] Support dual BIOS check command.

3. [Bug Fix] Fix the bug about remote setup error.

BIOS Release Notes

4. [Bug Fix] Fix the ECC/PERR/SERR incorrect SEL format.
-

D13

1. [Feature] Update RC 3218.D03 (BKC 2024 WW21)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_80000640
SRF C0 MCU : m_01_a06f3_13000132
 3. [Feature] VROC driver : 9.0.0.1230
 4. [Bug Fix] Fix the bug about BIOS recovery feature.
 5. [Bug Fix] Fix the bug about incorrect remote setup menu information.
-

D12

1. [Feature] Update RC 0031.D97 (BKC 2024 WW19)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_80000640
SRF C0 MCU : m_01_a06f3_13000132
 3. [Feature] VROC driver : 9.0.0.1230
 4. [Bug Fix] Fix the yellow device of com port.
-

D11

1. [Feature] Update VROC driver to 9.0.0.1230.
-

D10

1. [Bug Fix] Fixed USB ports show incorrect info.
-

D09

1. [Feature] Support Power Policy setup item.
 2. [Bug Fix] Update Mapping table version : 18.
-

D08

1. [Bug Fix] Fix the bug about hanging code at 0x92 during VMD enable.
-

D07

1. [Feature] Update RC 0031.D27 (BKC 2024 WW15)
2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_80000620
SRF C0 MCU : m_01_a06f3_13000132

BIOS Release Notes

3. [Feature] VROC driver : 9.0.0.1088

D06

1. [Feature] Update TI VR version : B3.

D05

1. [Bug Fix] Update TI VR version : B2.

D04

1. [Feature] Update RC 0030.D85 (BKC 2024 WW13)

2. [Feature] Update microcode:

SRF A0 MCU : m_01_a06f0_80000360

GNR A0 MCU : m_01_a06f0_80000611

SRF C0 MCU : m_01_a06f3_13000131

3. [Feature] VROC driver : 9.0.0.1088

D03

1. [Bug Fix] Fine tune release note information.

D02

1. [Bug Fix] Update mapping table : 17.

D01

1. [Feature] First release for DVT stage.

2. [Feature] Add TI VR version : B1.

3. [Feature] Update mapping table : 16.

E13

1. [Feature] Support SRF QS C0 stepping CPU.

E12

1. [Feature] Update RC 0030.D54 (BKC 2024 WW11)

2. [Feature] Update microcode:

SRF A0 MCU : m_01_a06f0_80000360

GNR A0 MCU : m_01_a06f0_80000600

3. [Feature] VROC driver : 9.0.0.1088

E11

1. [Bug Fix] Fix the bug about AFU (Linux) script.

BIOS Release Notes

E10

1. [Bug Fix] Update Mapping table version : 15.
-

E09

1. [Bug Fix] Update Mapping table version : 13.
-

E08

1. [Feature] Update RC 0030.D34 (BKC 2024 WW09)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_80000595
 3. [Feature] VROC driver : 9.0.0.1096
-

E07

1. [Bug Fix] Fix the bug about swtiching to BIOS2.
-

E06

1. [Feature] Update RC 0029.D87 (BKC 2024 WW07)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_800005c0
 3. [Feature] VROC driver : 9.0.0.1096
 4. [Feature] Update Mapping table setting.
-

E05

1. [Feature] Add Mapping table GPU feature set.
-

E04

1. [Feature] Update RC 0029.D28 (BKC 2024 WW05)
 2. [Feature] Update microcode:
GNR A0 MCU : m_01_a06f0_80000594
-

E03

1. [Feature] Fine tune MA94-FS0-000 bifurcation.
-

E02

1. [Bug Fix] Fixed present pin bifurcation error.
 2. [Bug Fix] Fixed one CPU hang on mapping table.
-

E01

BIOS Release Notes

1. [Feature] First EVT BIOS.
-