

# BIOS Release Notes

## TITLE

---

**SUBJECT:** MSF4-GP0 BIOS Release Notes version [F16](#)  
**System:** [MSF4-GP0-000](#), [R184-SF1-AAJ1-000](#), [R284-SF0-AAL1-000](#), [R284-SF1-AAL1-GB0](#), [R184-SF0-AAJ1-GB0](#), [R284-SF0-IAL1-000](#)

---

### About This Release

**Build Date:** [2024/11/14](#)  
**BIOS Checksum:** [0xB72A8AE3](#) (16M), [0x55878AC6](#) (64M)  
**Release Owner:** deann.wu

### BIOS Components/Contents

**Processor stepping(s) supported:** Intel® Granite Rapids-SP, Sierra Forest-SP processor  
**System hardware configurations supported:** MSF4-GP0  
**Microcode updates versions:**

CPUID	Family	Microcode Update ID
a06d0	Processor GNR A0	10000680
a06d1	Processor GNR B0	01000311
a06d1	Processor GNR R1S B0	1a000080
a06f3	Processor SRF C0	03000270

**IPMI support:**

**AMI Kernel version:** [Gbt\\_Kernel\\_064\\_21](#)

**Intel CSI/MRC Package version:** [3544P.08](#)

**OPROM version :**

OPROM	Version
AST2600 VGA	1.12.00
INTEL RAID PACKAGE	RSTe 9.0.0.1096

# BIOS Release Notes

## Installation Notes

### IMPORTANT NOTES:

1. Please extract the MSF4-GP0\_F16.zip to a bootable diskette that use FAT/FAT32 format

### BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

### BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.  
Or  
Enter \Tool\Win64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

### BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

### BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press <DEL> during POST
2. The bios version shows on the first main page

## Known Issues/Workarounds

## Issues fixed in this version

F16

1. [Feature] Update RC 3544P.08 (BKC 2024 WW43)
2. [Feature] Update microcode:  
GNR A0 MCU : m\_95\_a06d0\_10000680  
GNR B0 MCU : m\_95\_a06d1\_01000311

## BIOS Release Notes

GNR R1S B0 MCU : m\_20\_a06d1\_1a000080

SRF C0 MCU : m\_01\_a06f3\_03000270

3. [Feature] Update Mapping table : R16
- 

### F15

1. [Feature] Add intel patch for preventing boot failed with Samsung's specific dimms.
  2. [Bug Fix] Fix the bug about system will hang code after changing slot lanes.
  3. [Feature] Update Mapping table : R14
- 

### F14

1. [Feature] Support GNR R1S B0 stepping CPU
- 

### F13

1. [Feature] Update RC 34.D65 (BKC 2024 WW33)

2. [Feature] Update microcode:

GNR A0 MCU : m\_95\_a06d0\_80000670

GNR B0 MCU : m\_95\_a06d1\_810002e0

SRF C0 MCU : m\_01\_a06f3\_03000211

3. [Feature] VROC driver : 9.0.0.1096
  4. [Bug Fix] Fix the bug about incorrect ECC CE/UCE sel information.
- 

### F12

1. [Feature] Update SRF PROD/QS microcode : m\_01\_a06f3\_03000211
- 

### F11

1. [Feature] Update Mapping table V13.
- 

### F10

1. [Bug Fix] Fix the bug about PCIe device out of resource.
  2. [Feature] Update system mapping table V12.
- 

### F09

1. [Feature] Support SRF PRQ C0 stepping CPU.
- 

### F08

1. [Bug Fix] Fix the BUG about incorrect SVID.
  2. [Feature] Update mapping table version : R11.
- 

### F07

1. [Feature] Support dual BIOS check command.

## BIOS Release Notes

2. [Bug Fix] Fix the bug about remote setup error.
  3. [Bug Fix] Fix the ECC/PERR/SERR incorrect format.
- 

### F06

1. [Bug Fix] Fix the item "ACPI C1 Enumeration" not post to remote setup.
- 

### F05

1. [Feature] Update VR version : A4.
- 

### F04

1. [Feature] Update RC 3218.D03 (BKC 2024 WW21).
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000640  
SRF C0 MCU : m\_01\_a06f3\_13000132
  3. [Feature] VROC driver : 9.0.0.1096
  4. [Bug Fix] Fix the bug about BIOS recovery feature.
  5. [Bug Fix] Fix the bug about incorrect remote setup menu information.
- 

### F03

1. [Feature] Update Present pin setting
- 

### F02

1. [Feature] Update VR version : A3.
- 

### F01

1. [Feature] Update RC 0031.D97 (BKC 2024 WW19)
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000640  
SRF C0 MCU : m\_01\_a06f3\_13000132
  3. [Feature] VROC driver : 9.0.0.1096
  4. [Bug Fix] Fix yellow device of com port.
- 

### D23

1. [Bug Fix] Fix the bug about incorrect information on remote BIOS setup menu.
- 

### D22

1. [Bug Fix] Fixed USB ports show incorrect info.
-

# BIOS Release Notes

## D21

1. [Feature] Update mapping table v0.9.
- 

## D20

1. [Feature] Support Power Policy setup item.
- 

## D19

1. [Feature] Fix the bug about hanging code at 0x92 during VMD enable.
- 

## D18

1. [Feature] Update RC 0031.D27 (BKC 2024 WW15)
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000620  
SRF C0 MCU : m\_01\_a06f3\_13000132
  3. [Feature] VROC driver : 9.0.0.1096
- 

## D17

1. [Bug Fix] Fixed ECC sel log error.
- 

## D16

1. [Feature] Update RC 0030.D85 (BKC 2024 WW13)
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000611  
SRF C0 MCU : m\_01\_a06f3\_13000131
  3. [Feature] VROC driver : 9.0.0.1096
- 

## D15

1. [Bug Fix] Fine tune release note information.
- 

## D14

1. [Bug Fix] Fine tune WOL default setting to "Enable".
2. [Bug Fix] Fix SMBIOS Type 16 incorrect information.
3. [Bug Fix] Support "Power Button 1s shutdown" function under OS.
4. [Bug Fix] Fix IPv6 setting bug.
5. [Bug Fix] Fix ECC information during POST.
6. [Bug Fix] Fix NVMe port number incorrect in POST Text phase with VMD enable.
7. [Bug Fix] Fix Main page "Processor" incorrect information.
8. [Bug Fix] Fix ECC Bad DIMM will disappear after UCE occur.

## BIOS Release Notes

9. [Bug Fix] Fix SMBIOS Type 129 incorrect information.

---

D13

1. [Bug Fix] Fixed present pin bifurcation error.

---

D12

1. [Bug Fix] Because release VROC driver 9.0.0.1088 have bug, rollback VROC driver to 9.0.0.1096.

---

D11

1. [Feature] Support SRF QS C0 stepping CPU.

---

D10

1. [Feature] Update RC 0030.D54 (BKC 2024 WW11)

2. [Feature] Update microcode:

SRF A0 MCU : m\_01\_a06f0\_80000360

GNR A0 MCU : m\_01\_a06f0\_80000600

3. [Feature] VROC driver : 9.0.0.1088

---

D09

1. [Feature] Implement USB mapping.

---

D08

1. [Feature] Update VR MPS version : A2.

---

D07

1. [Bug Fix] Fix bug for lan disabled.

---

D06

1. [Feature] Update RC 0030.D34 (BKC 2024 WW09)

2. [Feature] Update microcode:

SRF A0 MCU : m\_01\_a06f0\_80000360

GNR A0 MCU : m\_01\_a06f0\_800005c0

3. [Feature] VROC driver : 9.0.0.1096

---

D05

1. [Bug Fix] Update mapping table v0.7

---

D04

1. [Feature] Update kernel 5.34\_0ACQZ\_29D87\_GNRSP\_SRFSP\_46

## BIOS Release Notes

2. [Feature] Update RC 0029.D87 (BKC 2024 WW07)

3. [Feature] Update microcode:

SRF A0 MCU : m\_01\_a06f0\_80000360

GNR A0 MCU : m\_01\_a06f0\_800005c0

4. [Feature] VROC driver : 9.0.0.1096

---

D03

1. [Feature] Add GPU SKU related feature set.

---

D02

1. [Bug Fix] Fixed ECC memory error.

2. [Feature] Add VMD & non-hotplug VMD feature.

---

D01

1. [Feature] Update RC 0029.D28 (BKC 2024 WW05)

2. [Feature] Update microcode:

SRF A0 MCU : m\_01\_a06f0\_80000351

GNR A0 MCU : m\_01\_a06f0\_80000593

---

E03

1. [Feature] Add first MPS VR solution : A1.

---

E02

1. [Feature] Add first MPS VR solution : A1.

---

E01

1. [Feature] First release.

---