

BIOS Release Notes

TITLE

SUBJECT: MS94-FS0 BIOS Release Notes version [F12](#)
System: [MS94-FS0-000](#), [R184-S91-AAV1-000](#), [MS94-FS0-00A](#), [R184-S90-AAV1-000](#),
[R184-S92-AAV1-000](#), [R184-S92-LAV1-000](#), [R184-S93-AAV1-GB0](#), [R284-S90-AAJ1-000](#), [R284-S92-AAJ1-000](#), [R284-S92-AAJ2-GB0](#), [R284-S90-AAJ2-GB0](#),
[R284-S94-AAJ1-GB0](#), [E284-S90-AAJ1-000](#), [R284-S93-AAL1-000](#), [R184-S94-AAV1-000](#), [R284-S91-AAJ1-000](#)

About This Release

Build Date: [2024/07/10](#)
BIOS Checksum: [0xF85BB12F](#) (16M), [0x96B87608](#) (64M)
Release Owner: lulu.chuang

BIOS Components/Contents

Processor stepping(s) supported: Intel® Granite Rapids-SP, Sierra Forest-SP processor

System hardware configurations supported: MS94-FS0

Microcode updates versions:

CPUID	Family	Microcode Update ID
a06d0	Processor GNR A0	80000640
a06f3	Processor SRF C0	030001b3

IPMI support:

AMI Kernel version: [Gbt_Kernel_053_26](#)

Intel CSI/MRC Package version: [3218.D03](#)

OPROM version :

OPROM	Version
AST2600 VGA	1.12.00
INTEL RAID PACKAGE	RSTe 9.0.0.1096

Installation Notes

BIOS Release Notes

IMPORTANT NOTES:

1. Please extract the MS94-FS0_F12.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.
Or
Enter \Tool\Win64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

Issues fixed in this version

F12

1. [Bug Fix] Fix the bug about PCIe device out of resource.
2. [Feature] Update system mapping table to version 36.

F11

1. [Bug Fix] Support SRF PRQ C0 stepping CPU.

F10

BIOS Release Notes

1. [Bug Fix] Fix the bug about incorrect SVID.
-

F09

1. [Feature] Support dual BIOS check command.
 2. [Bug Fix] Fix the bug about remote setup error.
 3. [Bug Fix] Fix the ECC/PERR/SERR incorrect format.
-

F08

1. [Feature] Update VR solution to version A3.
 2. [Bug Fix] Fix the item "ACPI C1 Enumeration" not post to remote setup.
-

F07

1. [Feature] Update RC 3218.D03 (BKC 2024 WW21)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_80000640
SRF C0 MCU : m_01_a06f3_13000132
 3. [Feature] VROC driver : 9.0.0.1096
 4. [Bug Fix] Fix the bug about BIOS recovery feature.
 5. [Bug Fix] Fix the bug about incorrect remote setup menu information.
-

F06

1. [Feature] Update RC 0031.D97 (BKC 2024 WW19)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_80000640
SRF C0 MCU : m_01_a06f3_13000132
 3. [Feature] VROC driver : 9.0.0.1096
 4. [Bug Fix] Fix yellow device of com port.
-

F05

1. [Bug Fix] Fix the bug about incorrect information on remote BIOS setup menu.
-

F04

1. [Feature] Set Trigger SW Error Threshold to Disable.
-

F03

1. [Bug Fix] Fixed USB ports show incorrect info.
-

F02

BIOS Release Notes

1. [Bug Fix] Fix Windows BSOD bug.
-

F01

1. [Feature] First PVT BIOS release.
-

D26

1. [Bug Fix] Fix the bug about randomly windows crash. (BSOD)
-

D25

1. [Feature] Update system mapping to version 33.
 2. [Bug Fix] Fix the bug about no TME related item.
-

D24

1. [Feature] Update system mapping table to version 32.
-

D22

1. [Bug Fix] Fix minor bugs.
-

D21

1. [Feature] Add Power Policy setup item.
 2. [Bug Fix] Update Mapping table version : 31
-

D20

1. [Bug Fix] Fix the bug about hanging code at 0x92 during VMD enable.
-

D19

1. [Feature] Update RC 0031.D27 (BKC 2024 WW15)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GMR A0 MCU : m_01_a06f0_80000620
SRF C0 MCU : m_01_a06f3_13000132
 3. [Feature] VROC driver : 9.0.0.1096
-

D18

1. [Bug Fix] Fixed ECC sel log error.
-

D17

1. [Feature] Update RC 0030.D85 (BKC 2024 WW13)
2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360

BIOS Release Notes

GNR A0 MCU : m_01_a06f0_80000611

SRF C0 MCU : m_01_a06f3_13000131

3. [Feature] VROC driver : 9.0.0.1096
-

D16

1. [Bug Fix] Fine tune release note information.
-

D15

1. [Feature] Fine tune WOL default setting to "Enable"
 2. [Bug Fix] Fix SMBIOS Type 16 incorrect information.
 3. [Feature] Support "Power Button 1s shutdown" function under OS.
 4. [Bug Fix] Fix IPV6 setting bug.
 5. [Bug Fix] Fix ECC information during POST.
 6. [Bug Fix] Fix NVMe port number incorrect in POST Text phase with VMD enable.
 7. [Bug Fix] Fix Main page "Processor" incorrect information.
 8. [Bug Fix] Fix ECC Bad DIMM will disappear after UCE occur.
 9. [Bug Fix] Fix SMBIOS Type 129 incorrect information.
-

D14

1. [Bug Fix] Because release VROC driver 9.0.0.1088 have bug, rollback VROC driver to 9.0.0.1096.
-

D13

1. [Feature] Support SRF QS C0 stepping CPU.
-

D12

1. [Feature] Update kernel 5.34_0ACQZ_30D54_SRFSP_48_BETA
2. [Feature] Update RC 0030.D54 (BKC 2024 WW11)
3. [Feature] Update microcode:

SRF A0 MCU : m_01_a06f0_80000360

GNR A0 MCU : m_01_a06f0_80000600

4. [Feature] VROC driver : 9.0.0.1088
-

D11

1. [Feature] Implement USB mapping.
-

D10

1. [Feature] Update Mapping table version : 29.
-

D09

BIOS Release Notes

1. [Feature] Add in system "R184-S92-LAV1-000".
-

D08

1. [Bug Fix] Fixed Lan disabled error.
-

D07

1. [Feature] Update RC 0030.D34 (BKC 2024 WW09)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_800005c0
 3. [Feature] VROC driver : 9.0.0.1096
 4. [Bug Fix] Update mapping table version : 28.
-

D06

1. [Feature] Update RC 0029.D87 (BKC 2024 WW07)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000360
GNR A0 MCU : m_01_a06f0_800005c0
 3. [Feature] VROC driver : 9.0.0.1096
-

D05

1. [Feature] Add GPU SKU related feature set.
-

D04

1. [Bug Fix] Fixed ECC memory error.
 2. [Feature] Add VMD & non-hotplug VMD feature.
-

D03

1. [Feature] Update MPS VR version : A2.
-

D02

1. [Feature] Update RC 0029.D28 (BKC 2024 WW05)
 2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000351
GNR A0 MCU : m_01_a06f0_80000593
 3. [Feature] Update MPS VR version : A1.
-

D01

1. [Feature] First DVT release BIOS.
-

BIOS Release Notes

E18

1. [Bug Fix] Fine tune MS94-FS0-00A SKU setting.
-

E17

1. [Bug Fix] Fixed present pin bifurcation error.
 2. [Bug Fix] Fixed one CPU hang on mapping table.
-

E16

1. [Feature] Fine tune Setup menu item.
-

E15

1. [Bug Fix] Fixed VPP settings solution.
-

E13

1. [Feature] Update system mapping table to version 17.
- system "R184-S91-AAV1-000" with BPB region.
-

E12

1. [Feature] Add BPB region into system mapping table for system "R184-S91-AAV1-000".
-

E11

1. [Feature] Modified OCP bifurcation ready GPIO setting.
-

E10

1. [Feature] Implement VPP settings.
 2. [Feature] Update the system mapping table to version 15.
-

E09

1. [Feature] Update VROC driver to 9.0.0.1096.
-

E08

1. [Bug Fix] Fix the bug about shell.efi not show correct information.
-

E07

1. [Feature] Update RC 2780.D02 (BKC 2023 WW47)
2. [Feature] Update microcode:
SRF A0 MCU : m_01_a06f0_80000340
GNR A0 MCU : m_01_a06f0_80000520
3. [Feature] VROC driver : 9.0.0.1044_2
4. [Feature] Support SRF CPU VROC.

BIOS Release Notes

E06

1. [Bug Fix] Fine tune OCP related GPIO setting.
-

E05

1. [Feature] Add first VR MPS solution.
-

E04

1. [Feature] Add SEC phase bifurcation setting.
 2. [Bug Fix] Modify vGPIO pins 80 ~ 83 GPIO reset config.
-

E03

1. [Bug Fix] Fix the bifurcation feature bug.
2. [Feature] Implement test version VR solution.

- Version: MSB4-G40 A1

E02

1. [Feature] Update system mapping to R14.
 2. [Bug Fix] Modified system bifurcation.
-

E01

1. [Feature] First release BIOS.
-