

# BIOS Release Notes

## TITLE

---

**SUBJECT:** MS33-AR0 BIOS Release Notes version [R06](#)

**System:** [MS33-AR0-000](#)

---

### About This Release

**Build Date:** [2024/05/06](#)

**BIOS Checksum:** [0xA66BD957](#) (16M), [0x8E742FA5](#) (64M)

**Release Owner:** jonas.hsu

### BIOS Components/Contents

**Processor stepping(s) supported:** Intel® Sapphire Rapids-SP/Emerald Rapids-SP processor

**System hardware configurations supported:** MS33-AR0

**Microcode updates versions:**

CPUID	Family	Microcode Update ID
806f3	Sapphire Rapids Production D-0	0d0004b1
806f8	Sapphire Rapids All HBM Production B	2c000390
806f8	Sapphire Rapids All Production XCC E / MCC S / EE LCC U	2b0005c0
c06f2	Processor Emerald Rapids Production XCC A1 / MCC R1	21000230

**IPMI support:**

**AMI Kernel version:** [Gbt\\_Kernel\\_102\\_22](#)

**Intel CSI/MRC Package version:** [109.D34](#)

**SPI Descriptor version:** [06.01.04.047.0](#)

**OPROM version :**

## BIOS Release Notes

OPROM	Version
INTEL 10G LAN EFI	7.0.19
INTEL 10G PXE	2.3.24
AST2600 VGA	1.12.00
INTEL RAID PACKAGE	RSTe 8.5.0.1096_2

### Installation Notes

#### IMPORTANT NOTES:

1. Please extract the MS33-AR0\_R06.zip to a bootable diskette that use FAT/FAT32 format

#### BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

#### BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.  
Or  
Enter \Tool\Win64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

#### BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

#### BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press <DEL> during POST
2. The bios version shows on the first main page

### Known Issues/Workarounds

# BIOS Release Notes

## Issues fixed in this version

### R06

1. [Feature] Fine tune Intel TDX related item.
  2. [Feature] Fine tune BMC IPv6 and IPv4 Network.
  3. [Feature] Include AMI SA50248 solution for CWE-119.
- 

### R05

1. [Feature] Update RC 109.D34 (EagleStream uPLR1 BKC 2024 WW12).
  2. [Feature] Update EMR Microcode : EMR Production A1/R1-Stepping:m\_87\_c06f2\_21000230.pdb;
  3. [Feature] Update SPR Microcode : SPR Production E-Stepping:m\_87\_806f8\_2b0005c0.pdb;SPR HBM Production B-Stepping:m\_10\_806f8\_2c000390.pdb;
  4. [Feature] Update SPS FW to SPS\_E5\_06.01.04.047.0.
  5. [Feature] Update BIOS ACM / SINT to v1.1.A.
  6. [Feature] Update TDX Module to TDX\_1.5.05.46.698.
  7. [Feature] Include INTEL-TA-01036 for CVE-2023-45745/CVE-2023-47855.
  8. [Feature] Include AMI SA50232 for CVE-2023-45236/CVE-2023-45237.
- 

### R04

1. [Bug Fix] Fix install CMT4032 can't downgrade to Gen3.
- 

### R03

1. [Feature] Update RC 1752.P05 (EagleStream UMR1 BKC 2024 WW05).
2. [Feature] Update EMR Microcode : No update.
3. [Feature] Update SPR Microcode : SPR Production E-Stepping:m\_87\_806f8\_2b000590.pdb;SPR HBM Production B-Stepping:m\_10\_806f8\_2c000360.pdb;
4. [Feature] Add AMI SA50218 for below CVE :  
CVE-2023-45229  
CVE-2023-45230  
CVE-2023-45231  
CVE-2023-45232  
CVE-2023-45233  
CVE-2023-45234  
CVE-2023-45235
5. [Feature] Add AMI SA50229 for CVE-2023-3817 and CVE-2023-2650.
6. [Feature] Add AMI SA50236 for CVE-2023-5678.

## BIOS Release Notes

---

### R02

1. [Feature] Update RC 107.D52 (EagleStream PV BKC 2023 WW49).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000200.pdb ; EMR Production A0-Stepping:Stepping:m\_87\_c06f2\_21000200.pdb;
  3. [Feature] Add AMI SA50216 solution for CVE-2023-39539 and CVE-2023-39538.
- 

### R01

1. [Feature] Update RC 107.D20 (EagleStream BKC 2023 WW45).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a10001d1.pdb .pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_210001B0.pdb; SPR Production E-Stepping:m\_87\_806f8\_2b000571.pdb;SPR HBM Production B-Stepping:m\_87\_806f8\_2c000351.pdb;
  3. [Feature] Update SPS to SPS\_E5\_06.01.04.005.0.
  4. [Feature] Update RSTe VROC driver to v8.5.0.1096.
- 

### T07

1. [Feature] Update RC 105.D74 (EagleStream BKC 2023 WW41).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000190.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000190.pdb; SPR Production E-Stepping:m\_87\_806f8\_2b000541.pdb;SPR HBM Production B-Stepping:m\_87\_806f8\_2c000321.pdb;
  3. [Feature] Update SPS to SPS\_E5\_06.01.04.003.0.
  4. [Feature] Update AST2600 vga/dp driver to 1.13.03 version.
- 

### T06

1. [Feature] Base on 2023 WW37 BKC release PC version BIOS.
- 

### T05

1. [Feature] Update RC 105.D74 (EagleStream BKC 2023 WW37).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000161.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000161.pdb;
- 

### T04

1. [Feature] Update RC 105.D48 (EagleStream BKC 2023 WW35).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000160.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000160.pdb;
  3. [Feature] Update VROC driver to v8.5.0.1074
- 

### T03

## BIOS Release Notes

1. [Feature] Update RC 105.D20 (EagleStream BKC 2023 WW33).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000150.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000140.pdb;
  3. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000150.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_21000140.pdb;
- 

### T02

1. [Feature] Update RC 103.D70 (EagleStream BKC 2023 WW27).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: m\_87\_c06f2\_a1000100.pdb ; EMR Production A0-Stepping:m\_87\_c06f2\_210000e0.pdb;
  3. [Feature] Update EMR SPS version to SPS\_E5\_06.01.02.048.0.
  4. [Feature] Update VROC driver to v8.5.0.1042.
- 

### T01

1. [Feature] Update RC 102.D37 (EagleStream BKC 2023 WW21).
  2. [Feature] Update EMR Microcode : EMR A0-Stepping: EMR A0-Stepping: m\_87\_c06f2\_a10000a0.pdb ; EMR Production A0-Stepping:m\_87\_c06f1\_21000070.pdb;
  3. [Feature] Update EMR SPS version to SPS\_E5\_06.01.02.009.0.
  4. [Feature] Update VROC driver to v8.5.0.1020.
-