

BIOS Release Notes

TITLE

SUBJECT: MRQ2-4S0 BIOS Release Notes version [F19](#)

System: [MRQ2-4S0-00](#), [R292-4S0-00](#), [R292-4S1-00](#)

About This Release

Build Date: [2023/05/29](#)

BIOS Checksum: [0xC83197B5](#) (32M), [0x5B6AE453](#) (64M)

Release Owner: willy.chen

BIOS Components/Contents

Processor stepping(s) supported: Intel® Cooper Lake-SP processors

System hardware configurations supported: MRQ2-4S0

Microcode updates versions:

CPUID	Family	Microcode Update ID
5065a	CooperLake A-0	86000020
5065b	CooperLake A-1	07002703

IPMI support:

AMI Kernel version: [Gbt_Kernel_023_01](#)

Intel CSI/MRC Package version: [23.P59](#)

SPI Descriptor version: [4.4.4.500](#)

OPROM version :

OPROM	Version
AST2500 VGA	1.03.05
INTEL RAID PACKAGE	RSTe 8.0.0.4006

Installation Notes

IMPORTANT NOTES:

1. Please extract the MRQ2-4S0_[F19](#).zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.

BIOS Release Notes

2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.
Or
Enter \Tool\Win64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

Issues fixed in this version

F19

1. [Feature] Update RC 23.P59 (CedarIsland BKC 2023.3 IPU-PV)
 2. [Feature] Update DCPMM UEFI driver v02.00.00.3887
 3. [Feature] Update microcode:
CooperLake A1 MCU : mbf5065b_07002703
 4. [Feature] Update ME : SPS_E5_04.04.04.301.0
 5. [Feature] Update VROC : v8.0.0.4006
 6. [Bug Fix] Update for security AMI SA50170
 7. [Bug Fix] Update for security AMI SA50162: CVE-2022-34301, CVE-2022-34302, CVE-2022-34303
-

F18

1. [Feature] Update RC 23.P45 (CedarIsland BKC 2023.2 IPU-PV)

BIOS Release Notes

2. [Feature] Update DCPMM UEFI driver v02.00.00.3887
 3. [Feature] Update microcode:
CooperLake A0 MCU : mbf5065a_86000020
CooperLake A1 MCU : mbf5065b_07002601
 4. [Feature] Update ME : SPS_E5_04.04.04.301.0
 5. [Feature] Update VROC : v7.8.0.1012
 6. [Feature] Fix INTEL-SA-00717 : CVE-2022-30539, CVE-2022-32231, CVE-2022-26837.
 7. [Feature] Fix INTEL-SA-00718 : CVE-2022-36348.
-

F17

1. [Bug Fix] Fix the bug about remote BIOS item on WEBUI.
-

F16

1. [Feature] Update RC 23.P27 (CedarIsland BKC 2022.1 IPU-PV)
 2. [Feature] Update DCPMM UEFI driver v02.00.00.3885
 3. [Feature] Update microcode:
CooperLake A0 MCU : mbf5065a_86000020
CooperLake A1 MCU : mbf5065b_07002501
 4. [Feature] Update ME : SPS_E5_04.04.04.104.0
 5. [Feature] Fix CVE-2021-33060(INTEL-SA-00601), CVE-2021-0159(INTEL-SA-00601), CVE-2021-33123(INTEL-SA-00601).
-

F15

1. [Bug Fix] Fix incorrect information on WEBUI PCIe info & HD info.
-

F14

1. [Bug Fix] Fix the bug about CPU sensor fail.
-

F13

1. [Feature] Update RC 23.P21 (CedarIsland BKC 2021.2 IPU-PV)
 2. [Feature] Update DCPMM UEFI driver v02.00.00.3878
 3. [Feature] Update microcode:
CooperLake A0 MCU : mbf5065a_86000020
CooperLake A1 MCU : mbf5065b_07002402
 4. [Feature] Update RSTe : v7.6.0.1012
 5. [Feature] Update VROC : v7.6.0.1012
 6. [Feature] Update ME : SPS_E5_04.04.04.028.0
-

F12

1. [Bug Fix] Fix SMBIOS table uncorrect information.

BIOS Release Notes

F11

1. [Bug Fix] Fix the bug about ECC.
-

F10

1. [Bug Fix] Fix Smbios Type131 string problem.
-

F09

1. [Feature] Fine tune onboard M.2 setting.
-