Firmware Ver1.0 update guide

Step1. Execute the update tool "FwUpdateTool.exe"

Step2. Click Next

Step3. Select "GIGABYTE,Gaming box, or GIGABYTE,1070IXEB" for the device and click next.

Step4. Click "Browse" to choose file

Thunderbolt FW Update Tool

- Welcome
- Select Controller/Device
- **Select FW Image**
- Confirmation
- Flashing...
- Done

Please choose file with new firmware for Thunderbolt(TM) control

[Browse]

[< Back] [Next >] [Cancel]

Step5. Select the corresponding file according to port1

Name	Date	Type	Size
AORUS_N1070IXEB_8GD_VER10.bin	2017/8/25 16:30	BIN 文件	300 KB
BNi5i7_TBT_FW_rev33_sign	2018/3/24 4:07	文件	300 KB
ECSIoDriver.sys	2017/11/14 21:34	系统文件	14 KB
ECSIoDriverX64.sys	2017/11/14 21:34	系统文件	14 KB
eHMTIoDriverLibrary.dll	2017/11/14 21:34	应用程序扩展	1,719 KB
FwUpdate.exe	2018/3/27 22:51	应用程序	1,727 KB
FwUpdateAPI.dll	2018/3/24 19:38	应用程序扩展	50 KB
FwUpdateTool.exe	2018/4/2 23:09	应用程序	473 KB
Gaming box update guide.pdf	2019/1/4 18:22	WPS PDF 文档	2,117 KB
Gigabyte_Gaming_Box_1.0_F1.0_for...	2019/1/14 13:50	BIN 文件	304 KB

名称	修改日期	类型	大小
AORUS_N1070IXEB_8GD_VER10.bin	2017/8/25 16:30	BIN 文件	300 KB
BNi5i7_TBT_FW_rev33_sign	2018/3/24 4:07	文件	300 KB
ECSIoDriver.sys	2017/11/14 21:34	系统文件	14 KB
ECSIoDriverX64.sys	2017/11/14 21:34	系统文件	14 KB
eHMTIoDriverLibrary.dll	2017/11/14 21:34	应用程序扩展	1,719 KB
FwUpdate.exe	2018/3/27 22:51	应用程序	1,727 KB
FwUpdateAPI.dll	2018/3/24 19:38	应用程序扩展	50 KB
FwUpdateTool.exe	2018/4/2 23:09	应用程序	473 KB
Gaming box update guide.pdf	2019/1/4 18:22	WPS PDF 文档	2,117 KB
Gigabyte_Gaming_Box_1.0_F1.0_for_Winbond.bin	2019/1/14 13:50	BIN 文件	304 KB

Step6. Click "Next"

Thunderbolt FW Update Tool ✕

Welcome	Please choose file with new firmware for Thunderbolt(TM) co
Select Controller/Device	C:\Users\jj\Desktop\AORUS-N1070IXEB-8GD-VER10\Gigabyte_Gamir [Browse]
Select FW Image	
Confirmation	
Flashing...	
Done	

< Back   [Next >]   Cancel

Step7. Click "Start Thunderbolt™ firmware update" to update

Step8. When the update is in process, please do not disconnect the Thunderbolt cable.

Step9. After the update is finish, please restart your PC.

Thunderbolt FW Update Tool

Welcome

Select Controller/Device

Select FW Image

Confirmation

Flashing...

Done

Firmware was updated successfully.

< Back   Next >   Cancel