

SCI65T BIOS Release Notes

TITLE

SUBJECT: SCI65T BIOS Release Notes version [F07](#)

About This Release

Build Date : July 10, 2013
BIOS Checksum : **SCI65T.F07 (2M): 0x15A858BF**
SCI65T_4.F07 (4M): 0x3584145B
Release Owner : Jack.Hsu

BIOS Components/Contents

Processor stepping(s) supported: supports Intel® Cedarview-D series processors

System hardware configurations supported: GC-SCI65T-00 Rev: 1.0

Microcodes update versions:

CPUID	Family	Microcode Update ID
30660	Cedarview-D	003
30661	Cedarview-D	10D

OPROM update versions:

OPROM	Version
IGFX VBIOS	1083
Intel RAID BIOS	10.6.0.1091
PXE ROM	1.3.65
ME FW	5.2.50.1039
MRC	1.0.0-3

ME firmware Update: **N/A**

Installation Notes

IMPORTANT NOTES:

1. Please extract the [SCI65T_F07.zip](#) to a bootable diskette that can boot to real DOS.
2. Please don't load HIMEM.SYS or any other memory management SW in the diskette.

BIOS UPDATE INSTRUCTIONS:

1. Copy the bios flash file to bootable USB flash key
2. Power on system and wait for boot into DOS
3. Execute F.BAT for bios update
4. After bios flash finish, it'll display a message

SCI65T BIOS Release Notes

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press F2 during POST.
2. Enter BIOS setup menu and go to Main page.
3. The bios version shows on this page.

Known Issues/Workarounds

1. Use external tool such as DediProg to flash the SPI flash with single 4MB binary file.
Warning: the external tool will erase entire flash before programming back with the new image, and cause the onboard 82567LM MAC address go back to default value. Use EEUPDATE.EXE to reprogram MAC address separately

Features added in this release

Features removed in this release.

Issues fixed in this version

1. Remove beep error when no keyboard/mouse connect.