

# BIOS Release Notes

## TITLE

**SUBJECT:** MS74-HB0 BIOS Release Notes version [F08](#)

**System:** [MS74-HB0-000](#)

### About This Release

**Build Date:** [2024/07/09](#)

**BIOS Checksum:** [0xF754322D](#) (16M), [0x95B0F706](#) (64M)

**Release Owner:** deann.wu

### BIOS Components/Contents

**Processor stepping(s) supported:** IntelR Granite Rapids-SP, Sierra Forest-SP processor

**System hardware configurations supported:** MS74-HB0

**Microcode updates versions:**

| CPUID | Family              | Microcode Update ID |
|-------|---------------------|---------------------|
| a06d0 | Processor GNR<br>A0 | 80000640            |
| a06f3 | Processor SRF<br>C0 | 030001b3            |

**IPMI support:**

**AMI Kernel version:** [Gbt\\_Kernel\\_053\\_26](#)

**Intel CSI/MRC Package version:** [3218.D03](#)

**OPROM version :**

| OPROM                 | Version         |
|-----------------------|-----------------|
| INTEL 1G PXE          | 1.5.53          |
| INTEL 1G LAN<br>EFI   | 8.5.21          |
| AST2600 VGA           | 1.12.00         |
| INTEL RAID<br>PACKAGE | RSTe 9.0.0.1096 |

### Installation Notes

**IMPORTANT NOTES:**

## BIOS Release Notes

1. Please extract the MS74-HB0\_F08.zip to a bootable diskette that use FAT/FAT32 format

### BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

### BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.  
Or  
Enter \Tool\Win64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

### BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

### BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press <DEL> during POST
2. The bios version shows on the first main page

## Known Issues/Workarounds

## Issues fixed in this version

### F08

1. [Bug Fix] Fix the bug about PCIe device out of resource.
- 

### F07

1. [Bug Fix] Fix the bug about wrong setup menu information.
- 

### F06

1. [Feature] Support SRF PRQ C0 stepping CPU.
-

# BIOS Release Notes

## F05

1. [Feature] Support dual BIOS check command.
  2. [Bug Fix] Fix the bug about remote setup error.
  3. [Bug Fix] Fix the ECC/PERR/SERR incorrect format.
- 

## F04

1. [Feature] Update VR version : A6.
- 

## F03

1. [Feature] Update RC 3218.D03 (BKC 2024 WW21).
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000640  
SRF C0 MCU : m\_01\_a06f3\_13000132
  3. [Feature] VROC driver : 9.0.0.1096
  4. [Bug Fix] Fix the bug about BIOS recovery feature.
  5. [Bug Fix] Fix the bug about incorrect remote setup menu information.
- 

## F02

1. [Feature] Update VR version : A5.
- 

## F01

1. [Feature] Update RC 0031.D97 (BKC 2024 WW19)
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000640  
SRF C0 MCU : m\_01\_a06f3\_13000132
  3. [Feature] VROC driver : 9.0.0.1096
  4. [Bug Fix] Fix yellow device of com port.
- 

## D20

1. [Bug Fix] Fix the bug about incorrect information on remote BIOS setup menu.
- 

## D19

1. [Bug Fix] Fixed USB ports show incorrect info.
- 

## D18

1. [Bug Fix] Fixed USB ports show incorrect info.
- 

## D17

# BIOS Release Notes

1. [Bug Fix] Fixed Window BSOD bug.
- 

## D16

1. [Bug Fix] Update Mapping table version : 03.
- 

## D15

1. [Feature] Support Power Policy setup item.
- 

## D14

1. [Feature] Fix the bug about hanging code at 0x92 during VMD enable.
- 

## D13

1. [Feature] Update RC 0031.D27 (BKC 2024 WW15)
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000620  
SRF C0 MCU : m\_01\_a06f3\_13000132
  3. [Feature] VROC driver : 9.0.0.1096
- 

## D12

1. [Feature] Update RC 0030.D85 (BKC 2024 WW13)
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000611  
SRF C0 MCU : m\_01\_a06f3\_13000131
  3. [Feature] VROC driver : 9.0.0.1096
- 

## D11

1. [Bug Fix] Fine tune release note information.
- 

## D10

1. [Bug Fix] Fine tune WOL default setting to "Enable".
2. [Bug Fix] Fix SMBIOS Type 16 incorrect information.
3. [Bug Fix] Support "Power Button 1s shutdown" function under OS.
4. [Bug Fix] Fix IPv6 setting bug.
5. [Bug Fix] Fix ECC information during POST.
6. [Bug Fix] Fix NVMe port number incorrect in POST Text phase with VMD enable.
7. [Bug Fix] Fix Main page "Processor" incorrect information.
8. [Bug Fix] Fix ECC Bad DIMM will disappear after UCE occur.
9. [Bug Fix] Fix SMBIOS Type 129 incorrect information.

# BIOS Release Notes

---

D09

1. [Feature] Update VR version : A4.
- 

D08

1. [Bug Fix] Because release VROC driver 9.0.0.1088 have bug, rollback VROC driver to 9.0.0.1096.
- 

D07

1. [Feature] Support SRF QS C0 stepping CPU.
- 

D06

1. [Feature] Update RC 0030.D54 (BKC 2024 WW11)
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_80000600
  3. [Feature] VROC driver : 9.0.0.1088
- 

D05

1. [Feature] Implement USB mapping.
- 

D04

1. [Feature] Update VR A3.
- 

D03

1. [Bug Fix] Fix bug for lan disabled.
- 

D02

1. [Feature] Update RC 0030.D34 (BKC 2024 WW09)
  2. [Feature] Update microcode:  
SRF A0 MCU : m\_01\_a06f0\_80000360  
GNR A0 MCU : m\_01\_a06f0\_800005c0
  3. [Feature] VROC driver : 9.0.0.1096
- 

D01

1. [Feature] First DVT release BIOS.
- 

E05

1. [Feature] Update RC 0029.D28 (BKC 2024 WW05)
2. [Feature] Update microcode:

## BIOS Release Notes

SRF A0 MCU : m\_01\_a06f0\_80000351

GNR A0 MCU : m\_01\_a06f0\_80000593

---

E04

1. [Feature] Update VR A2 Version I103.

---

E03

1. [Feature] Update VR Version : A1

---

E02

1. [Bug Fix] Fixed present pin bifurcation error.
2. [Bug Fix] Fixed one CPU hang on mapping table.

---

E01

1. [Feature] First release.
-