

BIOS Release Notes

TITLE

SUBJECT: MZ92-FS0 BIOS Release Notes version R16_F01
System: R282-Z93-00,R282-Z93-Q5

About This Release

Build Date: 2020/07/08
BIOS Checksum: 0xAA5B14DA(32M)
Release Owner: Candy.Wu

BIOS Components/Contents

Processor stepping(s) supported: AMD Rome Processors
System hardware configurations supported: MZ92-FS0
Microcode updates versions:

CPUID	Family	Microcode Update ID
Rome A0	Family 17h Model 30-3Fh	08300027
Rome B0	Family 17h Model 30-3Fh	08301038

IPMI support:
AMI Kernel version: 5.14_RomeCrb_0ACMK016
AGESA PI version: RomePI 1.0.0.7
OPROM version:

OPROM	Version
AST2500	1.09.00

Installation Notes

IMPORTANT NOTES:

1. Please extract the MZ92-FS0_R16_F01.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\Win32 and execute f.bat for Windows 32bit.

BIOS Release Notes

Or

Enter \Tool\Win64 and execute f.bat for Windows 64bit.

4. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

1. Windows OS does not support 256 or more logical.
Windows 2019 can update KB44512534 to support it.

item	OS	Win2019	Win2016
IOMMU		Enable ※	Enable KB4022723
SMT Control		Enable KB4512534	Disable

※When SMT Enabled, IOMMU need to set Enabled too.

SMT Control: AMD Simultaneous Multi-Threading Technology

KB4022723: Support IOMMU on Windows 2016.

KB4512534: Support SMT on Windows 2019.

2. NVIDIA CUDA didn't support IOMMU.

Issues fixed in this version

R16

1. Fixed system wait long time randomly when boot in OS.
2. Fixed redfish load boot order default fail.

R15

1. Update AGESA 1.0.0.7.
2. Change SMT & IOMMU Default to Auto & Enable
3. Adjust MZ92-FS1 USB driving.
4. Fixed Server manager setup setting message box lost.
5. Fixed PCIe device sequence.
6. Update redfish feature for boot order.

R14

BIOS Release Notes

1. Adjusted boot option maximum.
2. Adjusted R182-Z93-00 and R282-Z94-00 system PCIE link speed behavior.
3. Adjusted R182-Z93-00 and R282-Z94-00 system Hot-plug table.
4. Fixed M.2 missing in Linux with one CPU.
5. Update Redfish feature.
6. Core Performance Boost disable fail
7. Added onboard VGA default output priority option in UEFI mode.
8. BIOS Ready Timing change.
9. Fixed flash Naples BIOS crash issue.
10. Fixed IPMI Persistent Boot issue.

R13

1. Fixed Hot Plug function fail issue.
2. Adjusted R182-Z93-00 and R282-Z94-00 system PCIE link speed behavior.

R12

1. Update AGESA 1.0.0.6.
2. Added R182-Z93-00 and R282-Z94-00 system support.
3. Fine tune Redfish item.
4. Added Erp Lot 9 Item.
5. Fixed SVID issue.
6. Fixed IPMI command change boot order fail issue.
7. Fixed Shell screen re-flash issue.

R11

1. Update AGESA 1.0.0.5.
2. Fixed POST screen show wrong memory test error in CPU1 channel J.
3. Fixed SMBIOS Type 10.
4. Fixed NVDIMM hang at POST screen.
5. Fixed NVDIMM had exclamation mark in Windows.
6. Fixed X540 X550 PXE boot failed in Legacy mode.
7. Runtime disable turbo boost.
8. Added PCIE slot link speed control items.
9. Adjusted boot option label.
10. Adjusted XGMI Link Speed and remove unsupported options.

R10

1. Fixed NVIDIA and AMD GPU card driver BSOD issue.

R09

1. Update AGESA 1.0.0.4

BIOS Release Notes

2. Adjusted Setup Menu default.

R08

1. Update AGESA 1.0.0.3
2. Adjusted Setup Menu default.
3. Fine tune PCIe link speed behavior.

R07

1. Modify SMBIOS type131 data for Windows 2019 server HLK fail.
2. Default disable “HD Audio” for Windows 2019 server HLK fail.
3. Fixed Intel 82599 LAN card MAC address display issue.
4. Fixed 1 DIMM per channel ECC display issue.
5. Fixed legacy PXE boot issue.

R06

1. Modify USB device tree.
2. Fixed OCP2 slot issue.

R05

1. Update AGESA 1.0.0.2.
2. Add the remote modify BIOS setup function.
3. Fixed some slot hot plug fail issue.

R04

1. Fixed M.2 black screen issue.
2. Fixed low temperature hang issue.
3. Adjusted SATA Web information.
4. Adjusted R282-Z92-00 system default.

R03

1. Fixed SCE tool issue.
2. Adjusted OPR0M Option.
3. Adjusted NVMe Web information.

R02

1. Adjusted OPR0M Option.
2. Adjusted SLSAS and OCP2 link speed.
3. Adjusted Web UI information.

BIOS Release Notes

R01

1. First Release.
