

BIOS Release Notes

TITLE

SUBJECT: MZ32-AR0 BIOS Release Notes version R03b
System: R152-Z30-00,R152-Z31-00,R152-Z32-00,R272-Z30-00,R272-Z31-00,
R272-Z32-00

About This Release

Build Date: 2019/06/25
BIOS Checksum: 0x1A44AC9F2 (32M)
Release Owner: Candy.Wu

BIOS Components/Contents

Processor stepping(s) supported: AMD EPYC Rome Processors
System hardware configurations supported: MZ32-AR0-00,
Microcode updates versions:

CPUID	Family	Microcode Update ID
Rome A0	Family 17h Model 30-3Fh	08300027
Rome B0	Family 17h Model 30-3Fh	0830101C

IPMI support:
AMI Kernel version: 5.14_RomeCrb_0ACMK008
AGESA PI version: RomePI 1.0.0.0
OPROM version :

OPROM	Version
AST2500	1.09.0

Installation Notes

IMPORTANT NOTES:

1. Please extract the MZ32-AR0_R03b.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, please reboot system

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell
3. Execute \Tool\WIN\Win32*.bat or \Tool\Win64*.bat for bios update

BIOS Release Notes

4. After bios flash finish, please reboot system

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

1. Windows OS does not support 256 or more logical.
Windows 2019 can update KB4490481 to support it.

item	OS	Win2019	Win2016
IOMMU		Enable ※	Enable KB4022723
SMT Control		Enable KB4490481	Disable

※When SMT Enabled, IOMMU need to set Enabled too.

SMT Control: AMD Simultaneous Multi-Threading Technology

KB4022723: Support IOMMU on Windows 2016.

KB4490481: Support SMT on Windows 2019.

Issues fixed in this version

R03b

1. Add wait BMC item.
2. Adjust PPL.

R03a

1. Added SMBIOS 2.x Support.

R02

1. Fix the BMC about ECC display (Channel, DIMM).
2. Display the CECC or UECC on post report.
3. Fix 32MB hang 0x00d1.
4. Skip memory SMI error, when SMT control set disabled.

R02a

1. Update AGESA 1.0.0.0.
2. Add SKU list.
3. Adjust PCIe slot7 policy.

R01

1. Release PVT version.
2. Fix BMC IPv6 address cannot show on setup.