

BIOS Release Notes

TITLE

SUBJECT: MV13-HD0 BIOS Release Notes version [F07](#)
System: [MV13-HD0-000,H263-V11-LAW1-000,H223-V10-AAW1-000](#)

About This Release

Build Date: [2024/05/13](#)
BIOS Checksum: [0x9A4848DB](#) (32M)
Release Owner: Terry.Chuang / Daniel.Zheng

BIOS Components/Contents

Processor stepping(s) supported: NVIDIA Grace
System hardware configurations supported: MV13-HD0
PCB Version: 1.x
NVIDIA Firmware version: 01.02.04

OPROM version :

OPROM	Version
AST2600	1.13.03

Installation Notes

IMPORTANT NOTES:

- Please extract the MV13-HD0_F07.zip file to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

BIOS UPDATE INSTRUCTIONS FOR Web UI:

1. Connect BMC_IP by Internet browser.
2. Click Web-UI sub-page button "Update".
3. Select Firmware Type to ROM.
4. Use Command Shell.
5. Select File Path to *.fwpkg.
6. Click Upload.

BIOS UPDATE INSTRUCTIONS FOR GbtUtility:

1. Please copy the BIOS_ZIP file to GbtUtility folder.
2. Use Command Shell.
3. cd to GbtUtility folder.
4. Execute "java -jar GbtUtility.jar -H [BMC_IP](#) update bios [BIOS_ZIP](#) 1".

BIOS Release Notes

Known Issues/Workarounds

Issues fixed in this version

F07 (2024/05/13)

1. Update CVE Patch LogoFAIL CVE-2023-39539 and CVE-2023-39538.
2. Fix F05a BIOS chipset item not load default issue.

F07b (2024/05/06)

1. Update CVE Patch LogoFAIL CVE-2023-39539 and CVE-2023-39538.
2. Fix BIOS chipset item not load default issue.

F07a (2024/04/11)

1. Update NVIDIA Firmware 01.02.04
2. Fix IPv4 Static IP fail issue.
3. CVE Patch LogoFAIL CVE-2023-39539 and CVE-2023-39538.

F05 (2024/04/03)

1. Update NVIDIA Firmware 01.02.01
2. Enable Secure boot.
3. Fix IPv6 Static IP check fail issue.
4. Modify ASPM L1 default setting to disabled.
5. CVE patch OpenSSL for CVE-2023-2650, CVE-2023-3817, CVE-2023-5678.
6. CVE patch PixieFail IPv6 for CVE-2023-45229, CVE-2023-45230, CVE-2023-45231, CVE-2023-45232, CVE-2023-45233, CVE-2023-45234, CVE-2023-45235, CVE-2023-45236, CVE-2023-45237.

F05e (2024/04/01)

1. Enable Secure boot.
2. Fix IPv6 Static IP check fail issue.
3. Modify ASPM L1 default setting to disabled.
4. CVE patch OpenSSL for CVE-2023-2650, CVE-2023-3817, CVE-2023-5678.

F05d (2024/03/13)

1. Fix Power restore policy load default issue.

F05c (2024/03/05)

BIOS Release Notes

1. Fix PCIe Option ROM item failed issue.
2. Modify MVC3-MG0 M.2 NVMe order.
3. Set XV23-VC0 Power restore policy default power off.
4. Modify H263-V60 PCIe Slot name.

F05b (2024/03/05)

1. Modify ACPI OEM ID to NVIDIA.
2. Add more memory space for SMBIOS Type 45 of BMC FW info.
3. Set more info in SMBIOS Type 45 of TPM FW.

F05a (2024/02/23)

1. Update NVIDIA Firmware 01.02.01
2. Support MVC3-MG0 PCIe table.
3. Support Bad Date Time Error message on POST report.
4. CVE patch PixieFail IPv6 for CVE-2023-45229, CVE-2023-45230, CVE-2023-45231, CVE-2023-45232, CVE-2023-45233, CVE-2023-45234, CVE-2023-45235, CVE-2023-45236, CVE-2023-45237.

F04e (2024/01/30)

1. Fix some SKU not build SMBIOS Type9 problem.
2. Support Endless Retry PXE feature.
3. Modify MVC3-MG0 Uphy setting.

F04d (2024/01/26)

1. Support MVG3-MG0 Setup PCIe OPR0M switch item.
2. Support MGX Clear CMOS by removing battery or shorting jumper.
3. Enable http Url connections for http boot.

F04c (2024/01/23)

1. Modify CG1 Uphy3 Disable DPC at RP default to enabled.
2. Support MVG3-MG0 NVME sequence and SMBIOS Type 9.

F04b (2024/01/19)

1. Fix show failed message when flash the identical version BIOS under LINUX issue.
2. Fix BIOS setup BMC FW and BMC IP show N/A.
3. Fix POST not show IPMI FW version and IP address.

F04a (2024/01/18)

1. Update NVIDIA Firmware 01.01.04

BIOS Release Notes

2. Modify SMBIOS Type0 BIOS Characteristic.
3. Disable IPMI Power Save command.
4. Adjust CG1 NVME Port table pcie number to follow new PLX FW define.

F03b (2024/01/12)

1. Support AX88179 UEFI rom.
2. Support Mellanox CX3 Lan MAC feature.
3. Modify MV63-HD0 BIOS setup NVMe order.

F03a (2024/01/08)

- 1.Fixed some SKU not build SMBIOS Type9 problem
- 2.Support H/W Clear CMOS by removing CMOS Battery

F02 (2024/01/02)

1. Fix update BIOS FW under OS progress percentage incorrect issue when disable Logo.
2. Fix MV13-HD0 Onboard Lan option rom U.2 loss problem.
3. Adjust MV63-HD0 BIOS setup NVME order.
4. Fix SMBIOS Type129 NVMe information incorrect issue.

F02d (2023/12/27)

1. Support Setup PCIe OPRom switch item.
2. Fix WebUI DIMM Inventory info abnormal issue.

F02c (2023/12/14)

1. Support Grace Redfish remote setup.
2. Fix Setup NVME info did not show port name and wrong sequence problem.
3. Fix Setup IPv6 IP Address not found Issue.

F02b (2023/12/07)

1. Cancel Setup BMC LAN vendor check.

F02a (2023/12/06)

1. Fix BMC WebUI VGA device speed and width information incorrect issue.
 2. Fix BIOS Boot menu Onboard Lan naming abnormal when enable HTTP boot issue.
 3. Support Setup BMC Lan Mode Setting.
 4. Add NVIDIA firmware version in release note.
 5. Add POST Pause HotKey function.
-

BIOS Release Notes

F01 (2023/11/30)

1. PVT First release.
