



ChipsetINF_10083395650_1.zip

Vulnerability analysis verdict: PASS / Information leakage: PASS



0 Licenses

Components	7	Vulnerabilities	0	Licenses	0
Vulnerable	0	High	0	Copyleft	0
No known vulnerabilities	7	Medium	0	Permissive	0
		Low	0	Weak Copyleft	0
		Missing	0	Proprietary	0

Identified 3rd party components

Driver Install Frameworks API (DIFxAPI) 2.1
Intel.Deployment.ChipsetWiX.CustomAction 3.1.7.201
Intel.Tools 3.1.7.201
Intel.Tools.DeviceManager 3.1.7.201

Intel® Chipset Device Software 10.1.19928.8615
Windows Installer XML Toolset 3.14.1.8722
WixToolset.Dtf.WindowsInstaller 3.14.1.8722

Missing exploit mitigation techniques

Driver Install Frameworks API (DIFxAPI) 2.1

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.
ChipsetWiXCA.dll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.
ChipsetWiXCA.dll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/
Binary.ChipsetWiXCA.dll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/
Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chips etWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.Chips etWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chips etWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

Intel.Deployment.ChipsetWiX.CustomAction 3.1.7.201

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

no-buffer-security-check
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

no-buffer-security-check
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check

no-control-flow-guard

no-enforced-code-integrity

Intel.Tools 3.1.7.201

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chips etWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.Chips etWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binar y.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binar y.ChipsetWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chip setWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.Chip setWiXCA.dll/Intel.Tools.dll

no-buffer-security-check

no-control-flow-enforcement

no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Intel.Tools.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

Intel.Tools.DeviceManager 3.1.7.201

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chips etWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.Chips etWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chips etWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/DeviceManager.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

Intel® Chipset Device Software 10.1.19928.8615

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

Windows Installer XML Toolset 3.14.1.8722

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.

ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.

ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.

ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.

ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.

ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0
/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1
/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1
/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/
Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/
Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/
Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/
Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.Cab.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10083395650_1.zip/Chipset-10.1.19928.8615.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCA.dll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

Details

Original filename	ChipsetINF_10083395650_1.zip
SHA1 checksum	cd6f7f1f304754f39b1fd8a2716b8599af5e713a
Original file size	39.49 MB

Infoleak

Asymmetric keys:	0
AWS keys:	0
Custom pattern matches:	0
Emails:	0
HTTP authentication:	0
Image metadata:	0
IP addresses:	41
JSON web tokens:	0
MAC addresses:	0
OAuth tokens:	0
Passwords:	0
Shell history:	0
URLs:	0
Twilio keys:	0
Google cloud keys:	0
Facebook access tokens:	0