


ASRUS M6

Quick Guide


GETTING STARTED

- Please fully charge your mouse before using it for the first time.
- A depleted battery will be fully charged in approximately 3 hours.
- If your mouse has not been used for an extended period, you may need to recharge it before use.
- The mouse requires a USB connection that can supply sufficient power to charge the battery, and thisconnection also acts as the wired mode for your mouse.
- When charging begins after the charging cable is connected, the DPI indicator will show a static green light for 5 seconds.

How to activate the mouse?



How to charge the battery?



DPI indicator

Battery Percentage	DPI indicator Effect
<5%	Flashing red light continuously
<10%	Flashing red light for 5 seconds
<20%	Flashing red light for 5 seconds
20%-99%	No effect
100%	Static Green light (In charging mode)

 You can view more detailed battery status through the GIGABYTE Control Center.

DPI	DPI indicator light
800(Default)	White
1600	Yellow
3200	Cyan
6400	Magenta

 You can change your mouse's DPI to match your playstyle with a press of the DPI cycle button or fine-tune your own sensitivity setting using the GIGABYTE Control Center.