

BIOS Release Notes

TITLE

SUBJECT: MR83-AC0 BIOS Release Notes version F16
System: MR83-AC0-000,G383-R80-AAP1-000,G383-R80-LAP1-000,
G383-R80-LAP1-001

About This Release

Build Date: 2025/04/23
BIOS Checksum: 0x9CA5F9AA (32M)
Release Owner: Leon.Liang

BIOS Components/Contents

Processor stepping(s) supported: AMD EPYC CPU Family 19h Model
System hardware configurations supported: MR83-AC0-000
PCB Version: 1.x
Microcode updates versions:

CPUID	Family	Microcode Update ID
A0	Family 19h Model	0x0A90000B
A1	Family 19h Model	0x0A90010A

IPMI support:
AMI Kernel version: 5.33_0ACSD_PI1.0.0.9_024
AGESA PI version: MI300PI 1.0.0.9
OPROM version:

OPROM	Version
AST2600	1.12.00

Installation Notes

IMPORTANT NOTES:

1. Please extract the MR83-AC0_F16.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Execute F.nsh for bios update
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.

BIOS Release Notes

3. Enter \Tool\afuwin32 and execute f.bat for Windows 32bit.
Or
Enter \Tool\afuwin64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

Issues fixed in this version