

BIOS Release Notes

TITLE

SUBJECT: MZ43-G20 BIOS Release Notes version R14_F39
System: MZ43-G20-000,G293-Z40-AAP1-000,G293-Z41-AAP1-000,
G293-Z42-AAP1-000,G293-Z42-IAP1-000,G293-Z42-IAP1-C40,
G293-Z43-AAP1-000,TO15-Z40-AA01-000,TO15-Z40-IA01-000,
G294-Z41-AAP2-000,G294-Z42-AAP1-000,G294-Z42-AAP1-LM0,
G294-Z42-AAP2-000,G294-Z43-AAP2-000

About This Release

Build Date: 2025/03/21
BIOS Checksum: 0x72A45F5C (32M)
Release Owner: Hex.Jan

BIOS Components/Contents

Processor stepping(s) supported: AMD Turin / Genoa Processors
System hardware configurations supported: MZ43-G20-000
PCB Version: 1.x,3.x
Microcode updates versions:

CPUID	Family	Microcode Update ID
Turin A0	Family 1Ah Model 00h-0Fh	0x0B00004D
Turin B0	Family 1Ah Model 00h-0Fh	0x0B001016
Turin C0	Family 1Ah Model 00h-0Fh	0x0B002032
Turin C1	Family 1Ah Model 00h-0Fh	0x0B00211E
Turin Dense A0	Family 1Ah Model 00h-0Fh	0x0B10000F
Turin Dense B0	Family 1Ah Model 00h-0Fh	0x0B101028

IPMI support:
AMI Kernel version: 5.35_0ACST_PI1.0.0.3_017
AGESA PI version: TurinPI 1.0.0.3
OPROM version:

OPROM	Version
AST2600	1.13.00

Installation Notes

IMPORTANT NOTES:

1. Please extract the MZ43-G20_R14_F39.zip to a bootable diskette that use FAT/FAT32 format

BIOS Release Notes

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsX:", "X" is your USB filesystem number
4. Flash script for bios update:
 - 4.1 For AMD EPYC 9004 series CPU, execute f_GtoT.nsh
 - 4.2 For AMD EPYC 9005 series CPU, execute f.nsh
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. For AMD EPYC 9004 series CPU:
 - 3.1 Enter \Tool\WIN\afuwin32 and execute f_GtoT.bat for Windows 32bit.
 - 3.2 Enter \Tool\WIN\afuwin64 and execute f_GtoT.bat for Windows 64bit.
4. For AMD EPYC 9005 series CPU:
 - 4.1 Enter \Tool\WIN\afuwin32 and execute f.bat for Windows 32bit.
 - 4.2 Enter \Tool\WIN\afuwin64 and execute f.bat for Windows 64bit.
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

Issues fixed in this version

R14

- 1.[Fix] Fix PCIE compatibility when install GPU card.

R13

- 1.[Feature] Support G294-Z42-AAP1-LM0.

R12

- 1.[Feature] Support G293-Z42-IAP1-C40.

R11

- 1.[Feature] Adjust the default maximum DDR speed.

BIOS Release Notes

R10

1. [Fix] SCE tool import/export issue.
2. [Fix] Fix Redfish sends data twice after the system has completed booting.
3. [Feature] Adjust the maximum speed limit during automatic memory training.
4. [Feature] Add support for PCIe Re-Sizeable BAR functionality.

R09

1. [Feature] Optimize system compatibility.

R08

1. [Feature] Optimize system compatibility.

R07

- 1.[Fix] Optimize PCIe Resource assign.

R06

- 1.[Feature] Update AGESA 1.0.0.3.
- 2.[Feature] Support DDR speed up to 6400, but it requires manual adjustment in the BIOS settings.
UMC Common Options => Enforce POR => Accept => Memory Target Speed set [DDR6400]
- 3.[Fix] Fix the issue where NVMe speed is reduced to Gen4 after a hot plug.
- 4.[Fix] Fix the issue where SEL reports incorrect DDR channel information when associated with CPU1.
- 5.[Fix] Fix the issue where the system ready to boot process gets stuck when the BMC is unresponsive.

R05

1. [Support] Release turin BIOS for Genoa update.

R04

1. [Feature] Update AGESA 1.0.0.2.
2. [Fix] Fix the network configuration switching issue in the BIOS Server Manager setup.
3. [Fix] Fix the issue where having too many installed devices causes the system to hang at the BIOS logo screen.
4. [Feature] Update Invnetory v24.
5. [Feature] Optimize system SKU name for G494-Z4x system.
6. [Feature] Optimize re-driver and NVME hotplug for SKU name change.

BIOS Release Notes

7. [Feature] Enhance device compatibility.

R03

1. [Feature] Fixed LAN MAC Disabled fail.(Boadcom57416 lanmac show erro)

R02

- 1.[Feature] Fixed Post stage infomation.
- 2.[Feature] Sopport WHLK.

R01

- 1.[Feature] First Release.
 - 2.[Feature] 1.0.0.0 NDA_Patch3
-