

BIOS Release Notes

TITLE

SUBJECT: MZ62-HD4 BIOS Release Notes version M20_R33
System: MZ62-HD4-00,H262-Z6A-00,H262-Z6B-00,H262-ZL0-00,H262-ZL2-00,
H282-Z60-00,H262-ZLA-NJ2,H262-Z6B-ICP1-000,H262-Z6B-ICU1-000,
H262-Z6B-ICP2-IX0

About This Release

Build Date: 2024/07/11
BIOS Checksum: 0x8BBC65F9 (32M)
Release Owner: Auto.Build(Ray.Xu)

BIOS Components/Contents

Processor stepping(s) supported: AMD Milan / Rome Processors
System hardware configurations supported: MZ62-HD4-00
PCB Version: 3.x
Microcode updates versions:

| CPUID | Family | Microcode Update ID |
|----------|-------------------------|---------------------|
| Milan A0 | Family 19h Model 00-0Fh | 0A000033 |
| Milan B0 | Family 19h Model 00-0Fh | 0A001079 |
| Milan B1 | Family 19h Model 00-0Fh | 0A0011D3 |
| Milan B2 | Family 19h Model 00-0Fh | 0A001236 |

IPMI support:
AMI Kernel version: 5.22_MilanCrb_0ACOU024
AGESA PI version: MilanPI 1.0.0.C
OPROM version:

| OPROM | Version |
|---------|---------|
| AST2500 | 1.10.00 |

Installation Notes

IMPORTANT NOTES:

1. Please extract the MZ62-HD4_M20_R33.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.
3. Enter your USB filesystem, like "fs0:" or "fsX:", "X" is your USB filesystem number
4. Execute F.nsh for bios update

BIOS Release Notes

5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. Enter \Tool\afuwin32 and execute f.bat for Windows 32bit.
Or
Enter \Tool\afuwin64 and execute f.bat for Windows 64bit.
4. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

1. Windows OS does not support 256 or more logical.
Windows 2019 can update KB44512534 to support it.

| OS item | Win2019 | Win2016 |
|-------------|---------------------|---------------------|
| IOMMU | Enable ※ | Enable KB4022723 |
| SMT Control | Enable KB4512534 | Disable |

※When SMT Enabled, IOMMU need to set Enabled too.

SMT Control: AMD Simultaneous Multi-Threading Technology

KB4022723: Support IOMMU on Windows 2016.

KB4512534: Support SMT on Windows 2019.

2. NVIDIA CUDA didn't support IOMMU.

Issues fixed in this version

M20

1. [Feature] Fine tune BMC IPv6 and IPv4 Network.

M19

1. Enhance Endless Retry PXE feature.

M18

1. Update AGESA 1.0.0.C.

BIOS Release Notes

2. Security update: CVE-2023-39538, CVE-2023-39539, CVE-2023-45229, CVE-2023-45230, CVE-2023-45231, CVE-2023-45232, CVE-2023-45233, CVE-2023-45234, CVE-2023-45235.

M17

1. Update AGESA 1.0.0.A.
2. Update Rome ucode 0830107A for CVE-2023-20593 issue.

M16

1. Update AMD Rome AGESA 1.0.0.E.

M15

1. Update AGESA 1.0.0.9.
2. Added H262-Z6B-ICP2-IX0 system support.

M14

1. Update IR Version to 8168.
2. Added system H262-Z6B-ICU1-000, H262-Z6B-ICP1-000 support.
3. Change AC Loss default to Power On.
4. Update AGESA 1.0.0.7.

M13

1. Added H262-ZLA-NJ2 system support.

M12

1. Fixed HDD amber led issue

M10

1. Update AGESA 1.0.0.6.
2. Update microcode.

M09

1. Update microcode.
 2. Set BIOS setup [Power Quick Setting] default to [Standard] mode.
 3. Fixed redfish lost character.
 4. Fixed the SVID number on some PCIE.
-

BIOS Release Notes

M08

1. Fine tune flash tool for dual BIOS.
 2. Support NVME LED control for system.
 3. Modify BMC major number format in setup menu.
-

M07

1. Update AGESA 1.0.0.4.
 2. Fixed afu check second BIOS rom failed.
 3. Fixed Qlogic MAC issue in WebUI.
 4. Adjusted G262-ZRA-SU/G262-ZL0-00 Onboard LAN.
 5. Added system G262-ZO0.
-

M06

1. Fixed SMBIOS broken.
 2. Added G262-ZL0-00.
-

M05

1. Fixed performance lower issue.
 2. Added H282-Z60 nvme hot plug function.
 3. Updated RedFish - System Inventory
 4. Update SMBIOS Type 130,131.
 5. Added G262-ZRA-SU
-

M04

1. Update AGESA 1.0.0.2.
 2. Fixed system reboot hang with TPM module.
-

M03

1. Update AGESA 1.0.0.1
 2. Fixed some graphic card will hang on Legacy mode.
 3. Fixed Redfish upload fail.
 4. Fixed some lan card hang code.
 5. Fixed Redfish can't remote TER000 item.
 6. Fixed GenZ_1 slot is always x16 issue.
-

M02

- 1.Updated AGESA 1.0.0.0.
-

M01

BIOS Release Notes

1. First release.
-