


GTX1060 have two BIOS and should change to different port when BIOS flashing, please refer as below:

AX6D BIOS FLASHING(with DVI-D Port)



AX6H BIOS FLASHING(with HDMI and DP)

