



**Caution!! During the firmware update, please do not execute any other application and remove all USB devices on the box.**

## Firmware Ver1.0 update guide



### Step1. Execute the update tool “FwUpdateTool.exe”




### Step2. Click Next




Step3. Select "GIGABYTE,Gaming box, or GIGABYTE,1070IXEB" for the device and click next.




Step4. Click "Browse" to choose file




Step5. Select the corresponding file according to port1







Step6. Click "Next"



Step7. Click “Start Thunderbolt™ firmware update” to update



Step8. When the update is in process, please do not disconnect the Thunderbolt cable.



Step9. After the update is finish, please restart your PC.





Welcome

Firmware was updated successfully.

Select  
Controller/Device

Select FW Image

Confirmation

Flashing...

Done

< Back

Next >

Cancel